REMARKS

The Applicants have amended FIG. 4 to correct an inconsistency with respect to OPAMP 414. As with OPAMPs 410 and 412 and resistors 436 and 442, a resistor 437 is connected between the output of OPAMP 414 and the negative input terminal of OPAMP 414. The resistor 437 was inadvertently omitted from FIG. 4 as filed. As depicted in FIG. 4 and described in the application, the three OPAMPs 410, 412 and 414 are similarly positioned to drive the left (L) channel signal 112, the right (R) channel 110 and the common mode (CM) signal 114, respectively. [Specification, page 10, lines 11-14]. This amendment adds no new matter to the application.

Should any fees under 37 CRF 1.16-1.21 be required for any reason relating to the enclosed materials, the Commissioner is authorized to deduct such fees from Jones, O'Keefe, Egan & Peterman Deposit Account No. 10-1205/CRYS:011. The examiner is invited to contact the undersigned at the phone number indicated below with any questions or comments, or to otherwise facilitate expeditious and compact prosecution of the application.

Respectfully submitted,

Brian W. Peterman

Registration No. 37,908

Attorney for Applicant

JONES, O'KEEFE, EGAN & PETERMAN LLP 1101 Capital of Texas Highway South

Building C, Suite 200

Austin, Texas 78746

(512) 347-1611

FAX: (512) 347-1615



